

SL-18

SL-18-LO-A

SL-18-LE-B

Riparian Unit and Shoreline Assessment Data Form

Shoreline/Riparian Unit ID: 18

Date: 4-19-17

Coordinates- Start

Coordinates- End

Surveyor(s): MK, TM

Unit Length

Assessment Method

RECON (BOAT) SITE INSPECTION

Reaches within Unit: 18a

Additional Features within Unit: There are some washes w/ topographic valleys, however no riparian/ Wetland present, thus no lotic/lentic for those washes.

Obtain from GIS

Community Type (Source):

Mixed Chaparral (Calveg)

VEGETATION

Dominant Over-Story (Species/% Cover)	Dom Mid-Strata (Species/% Cover)	Dom Over-Story (Species/% Cover)
Manzanita	none	BROTEC
Chamise		ERIEGNUM SP.
SCRUB OAK		
JURCA		
Clinton wood		
Saliv spp. / Various		

HYDROLOGY

Description of Hydrologic Regime: LACUSTRINE. UNIFORM High Water Mark VISIBLE Along Shoreline. Water consistently below stream. Area exhibits hydrologic conditions indicative of seasonal/Climate Lake use/fall.

LANDSCAPE

Description of geomorphic regime (erosion processes, upland condition, substrate, etc): SHORELINE IS COMPRISED OF SANDY BEACHES, w/ intermittent rock outcroppings. Primary substrate comprised of fine sand debris and cobbles. Various bare areas littered w/ woody debris. Slopes are generally sloping uniformly.

OTHER INFORMATION

Unit Assessment Rational: vegetated uplands as you move upslope from waterline. This area is one unit as it is comprised of uniform vegetation, geomorphology, and hydrologic features. Uniform lateral gradient.

Additional Notes

North shore of Lake Silverwood, south facing slope.

