

SL-22
 no associated lentic
 or lotic features

Riparian Unit and Shoreline Assessment Data Form

Shoreline/ Riparian Unit ID: 122 Date: 4-20-2017
 Coordinates- Start: _____ Coordinates- End: _____ Surveyor(s): MK, IM, MG
 Unit Length: _____ Assessment Method: Reconnaissance via Boat
 Reaches within Unit: _____
 Additional Features within Unit: _____

VEGETATION

Community Type (Source): Chaparral - scrub shrub dominant

Dominant Over-Story (Species/% Cover)	Dom. Mid-Strata (Species/% Cover)	Dom. Under-Story (Species/% Cover)
<u>none noted</u>		

HYDROLOGY

Description of Hydrologic Regime: _____

LANDSCAPE

Description of geomorphic regime (erosion processes, upland condition, substrate, etc): Rocky shoreline = adequate to
dissipate wave energy

OTHER INFORMATION

Unit Assessment Rational: No adequate riparian vegetation cover = only
shoreline unit w/ no lentic or lotic feature.

Additional Notes: _____

